

Customer Release Notes

Fabric Engine

Software Release 8.6.1.2

August 2022

INTRODUCTION:

This document describes important information about this release for platforms that support Extreme Networks Fabric Engine™.

The purpose of this version is to address customer and internally found software issues.

Newly Purchased Switches Require Software Upgrade. You should promptly upgrade the Fabric Engine software to the latest version available by visiting the Extreme Portal.

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at:
www.extremenetworks.com/support/

NEW IN THIS RELEASE:

Please see “New Features in this release” section below for more information.

IMPORTANT NOTES BEFORE UPGRADING TO THIS RELEASE:

Please see “Fabric Engine Release Notes for version 8.6.1” available at <https://www.extremenetworks.com/support/release-notes> for details about upgrading.

UPGRADE CONSIDERATIONS WHEN UPGRADING TO 8.6.1.2 FROM PREVIOUS RELEASES:

Please see “Fabric Engine Release Notes for version 8.6.1” available at <https://www.extremenetworks.com/support/release-notes> for details about upgrading.

PLATFORMS SUPPORTED:

Please see “Fabric Engine Release Notes for version 8.6.1” available at <https://www.extremenetworks.com/support/release-notes> for details regarding supported platforms.

FILE NAMES FOR THIS RELEASE:

Extreme Switching 5320 Series

File Name	Module or File Type	File Size (bytes)
5320.8.6.1.2_edoc.tar	Logs Reference	64061440
5320.8.6.1.2.md5	MD5 Checksums	461
5320.8.6.1.2_mib_sup.txt	MIB - supported object names	1525848
5320.8.6.1.2_mib.txt	MIB - objects in the OID compile order	8159168
5320.8.6.1.2_mib.zip	Archive of all MIB files	1219154
5320.8.6.1.2_oss-notice.html	Open source software - Master copyright file	2785868
5320.8.6.1.2.sha512	SHA512 Checksums	1376
5320.8.6.1.2.voss	Software image	102457860
FabricEnginev860_HELP_EDM_gzip.zip	EDM Help file	4613738
restconf_yang.tgz	YANG model	506020

Extreme Switching 5420 Series

File Name	Module or File Type	File Size (bytes)
5420.8.6.1.2_edoc.tar	Logs Reference	64061440
5420.8.6.1.2.md5	MD5 Checksums	461
5420.8.6.1.2_mib_sup.txt	MIB - supported object names	1524924
5420.8.6.1.2_mib.txt	MIB - objects in the OID compile order	8159168
5420.8.6.1.2_mib.zip	Archive of all MIB files	1219154
5420.8.6.1.2_oss-notice.html	Open source software - Master copyright file	2785868
5420.8.6.1.2.sha512	SHA512 Checksums	1376
5420.8.6.1.2.voss	Software image	102071674
FabricEnginev860_HELP_EDM_gzip.zip	EDM Help file	4613738
restconf_yang.tgz	YANG model	506020

Extreme Switching 5520 Series

File Name	Module or File Type	File Size (bytes)
5520.8.6.1.2_edoc.tar	Logs Reference	64061440
5520.8.6.1.2.md5	MD5 Checksums	461
5520.8.6.1.2_mib_sup.txt	MIB - supported object names	1525481
5520.8.6.1.2_mib.txt	MIB - objects in the OID compile order	8159168
5520.8.6.1.2_mib.zip	Archive of all MIB files	1219154
5520.8.6.1.2_oss-notice.html	Open source software - Master copyright file	2785868
5520.8.6.1.2.sha512	SHA512 Checksums	1376
5520.8.6.1.2.voss	Software image	106045084

File Name	Module or File Type	File Size (bytes)
FabricEnginev860_HELP_EDM_gzip.zip	EDM Help file	4613738
restconf_yang.tgz	YANG model	506020

Note about image download:

Ensure images are downloaded using the binary file transfer. Perform MD5 checksum check on downloaded files to ensure file integrity.

Check that the file type suffix is “.tgz” and the image names after download to device match those shown in the above table. Some download utilities have been observed to append “.tar” to the file name or change the filename extension from “.tgz” to “.tar”. If file type suffix is “.tar” or file name does not exactly match the names shown in above table, rename the downloaded file to the name shown in the table above so that the activation procedures will operate properly.

Load activation procedures:

```
software add 5520.8.6.1.2.voss
software activate 8.6.1.2.GA
```

or

```
software add 5420.8.6.1.2.voss
software activate 8.6.1.2.GA
```

or

```
software add 5320.8.6.1.2.voss
software activate 8.6.1.2.GA
```

COMPATIBILITY:

This software release is managed with Enterprise Device Manager (EDM), which is integrated into the agent software.

CHANGES IN THIS RELEASE:**New Features in This Release**

None

Old Features Removed From This Release

None

Problems Resolved in This Release

VOSS-26723	Out of memory crash might be encountered due to a flaw in the logging handling code
------------	---

Fixes from Previous Releases

Fabric Engine 8.6.1.2 incorporates all fixes from prior releases, up to and including VOSS 8.4.3.0, VOSS 8.5.1.0 (VOSS 8.5.2.0 fixes are **not** included in Fabric Engine 8.6.1.2) and Fabric Engine 8.6.1.1.

OUTSTANDING ISSUES:

Please see “Fabric Engine Release Notes for version 8.6.1” available at <https://www.extremenetworks.com/support/release-notes> for details regarding Known Issues.

KNOWN LIMITATIONS:

Please see “Fabric Engine Release Notes for version 8.6.1” available at <https://www.extremenetworks.com/support/release-notes> for details regarding Known Limitations.

Regular cleanup of unneeded files on USB drives is recommended to minimize possibility of USB corruption when a system is reset, shut down, or power is lost.

DOCUMENTATION CORRECTIONS:

For other known issues, please refer to the product release notes and technical documentation available at: <https://www.extremenetworks.com/support/documentation>.

GLOBAL SUPPORT

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country:
www.extremenetworks.com/support/

By Email: support@extremenetworks.com

By Web: www.extremenetworks.com/support/

By Mail: Extreme Networks, Inc.
6480 Via Del Oro
San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Copyright © 2022 Extreme Networks, Inc. - All Rights Reserved.

Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice.

Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners.

For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks