

IQ Engine 10.1r2 Release Notes

Release date: January 23, 2020

Hardware platforms supported: AP305C, AP305CX, AP410C, and AP410CX

Management platforms supported: ExtremeCloud IQ 20.1.1.1 and later

New Features and Enhancements

This release introduces the following new features and enhancements:

New Hardware Support: IQ Engine 10.1r1 features support for the new AP410C and AP410CX.

ⓘ This release of IQ Engine does not currently support 802.11ax features on 802.11ax devices.

Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.1.

Known Issues in IQ Engine 10.1r2

HOS-15762	The interference value sometimes differs from the real-time interference channel utilization value.
-----------	---

Addressed Issues in IQ Engine 10.1r2

CFD-4453	Disconnecting a client from a WPA3 SSID caused all other clients to disconnect.
----------	---

Addressed Issues in IQ Engine 10.1r1

CFD-4300	When an AP underwent a scheduled reboot, client devices were disconnected from the wireless network.
----------	--

