
Juniper Networks, Inc. Copyright (c) 2012 All Rights Reserved

Mobility System Software 7.3.6.5 Release Notes

The following items are addressed in this MSS release:

690717 - 2.4GHz radios displayed radio utilization at 200%. 669785 - confidential (issue found during testing) 686040 - not all MIBs were working after upgrading to 7.3.5.2 700756 - a WLA522 issue resolved for University of Northern Iowa