

## Service Release Notes for WiNG 7.3.0.3-003R

**Please Note:** Service releases are made available to fix specific customer reported issues in a timely manner. Service releases are not as extensively tested as main releases (such as 7.3.0.0-038R). The next maintenance or manufacturing release will incorporate all qualifying and preceding service releases.

This document is an addendum to the release notes for the main release 7.3.0.0-038R.

### CONTENTS

<b>1. Resolved Issues .....</b>	<b>1</b>
<b>2. Important Notes.....</b>	<b>1</b>
<b>3. Platforms Supported .....</b>	<b>1</b>
<b>4. Firmware Upgrade/Downgrade Procedure .....</b>	<b>2</b>

### 1. RESOLVED ISSUES

This service release 7.3.0.3-003R is released with the XCA 4.76.02.0030.

Following is a list of SPRs/CRs fixed in this release:

CRID	Description
WING-42684	Resolved incorrect minimum basic rates being advertised in beacon for AP510 when managed by XCA.
WING-42690	Addressed Kr00k vulnerability (CVE-2019-15126)
WING-42682	Windows 10 PC is de-authenticated in 10 seconds

### 2. IMPORTANT NOTES

Please refer to XCA 4.76.02.0030 documentation for more information.

### 3. PLATFORMS SUPPORTED

This release applies to all platforms released with WiNG 7.3.0.3-003R.

#### 4. FIRMWARE UPGRADE/DOWNGRADE PROCEDURE

The method described in this section uses the Command Line Interface (CLI) procedures. To log into the CLI, either SSH, Telnet or serial access can be used.

**For detailed upgrade procedure – please refer to WiNG 7.3.0 release notes.**

##### Upgrade from WiNG v7.x.x to WiNG v7.3.0.3

1. Copy the controller image to your tftp/ftp server.
2. Use the **—upgrade ftp://<username>:<password>@<ip address of server>/<name of file>||**, or **—upgrade tftp://<ip address of server>/<name of file>** command from CLI or **Switch->Firmware->Update Firmware** option from the GUI. You may need to specify the username and password for your ftp server.
3. Restart the controller. From CLI the command is **—reload**.