

# **Customer Release Notes**

### **Ethernet Routing Switch 3600 Series**

Software Release 6.3.3 April 2020

#### **INTRODUCTION:**

This document provides specific information for version 6.3.3 of agent software for the Ethernet Routing Switch 3600 Series (All models).

The purpose of this version is to address customer and internally found software issues.

Extreme Networks recommends that you thoroughly review this document prior to installing or upgrading this product.

For the latest firmware versions, visit the download site at: <u>www.extremenetworks.com/support/</u>

#### IMPORTANT NOTES BEFORE UPGRADING TO THIS RELEASE

None.

#### PLATFORMS SUPPORTED

Ethernet Routing Switch 3600 Series (All models)

#### NOTES FOR UPGRADE

Please see "Configuring Systems on Ethernet Routing Switch 3600 Series", available at <u>https://www.extremenetworks.com/documentation</u> for details on how to upgrade your Switch.

#### FILE NAMES FOR THIS RELEASE

File Name	Module or File Type	File Size (bytes)
3600_6100_diags.bin	Diagnostic software	7096948
ers3600_633011s.img	SSH runtime image	15593152
ers3600v630_HELP_EDM.zip	EDM Help file zip	1678595
Ethernet_Routing_Switch_36xx_MIBs_6.3.0.zip	MIB definition files	1567297
ers3600v6.3.0.0.zip	COM Plug in file zip	4196321

#### VERSION OF PREVIOUS RELEASE

Software Version 6.3.2

04/09/2020 P/N: 9036699-00

#### COMPATIBILITY

This software release is managed with Enterprise Device Manager (EDM), which is integrated into the agent software.

#### **CHANGES IN THIS RELEASE**

#### New Features in This Release

None.

## Old Features Removed From This Release

None.

Problems Resolved in This Release		
ERS3600-812	ERS 3626GTS-PWR+: Intermittently the fans start running at full speed when switching to low power mode. This can happen either at startup when low power mode has been previously configured, or when changing the power mode during normal operation.	

#### **KNOWN LIMITATIONS:**

ERS3600-556 - EDM: Users can't connect on switch via secure EDM using Chrome version 59.

**Problem description**: Starting with version 59, Chrome reports the self-signed certificate issued by ERS family as having bad format and will fail to connect via secure EDM.

Workaround: Use Firefox (v74 or older), IE (v11 or older), Edge (v44 or older) or Chrome (v58 or older)

For other previously known issues, please refer to the product release notes and technical documentation available from the Extreme Networks Support web site at: <u>www.extremenetworks.com/support/</u>.

#### **DOCUMENTATION CORRECTIONS**

None.

#### TROUBLESHOOTING

As good practices of help for troubleshooting various issues, we recommend:

- configuring the device to use the Simple Network Time Protocol to synchronize the device clock;
- setting a remote logging server to capture all level logs, including informational ones. (#logging remote level informational).
- enabling timestamps on all show commands using the cli timestamp enable command

### **GLOBAL SUPPORT:**

By Phone: +1 800-998-2408 (toll-free in U.S. and Canada)

For the toll-free support number in your country: <a href="http://www.extremenetworks.com/support/">www.extremenetworks.com/support/</a>

- By Email: <a href="mailto:support@extremenetworks.com">support@extremenetworks.com</a>
- By Web: www.extremenetworks.com/support/
- By Mail: Extreme Networks, Inc. 6480 Via Del Oro San Jose, CA 95119

For information regarding the latest software available, recent release note revisions, or if you require additional assistance, please visit the Extreme Networks Support website.

Copyright © 2020 Extreme Networks, Inc. - All Rights Reserved.

#### Legal Notice

Extreme Networks, Inc. reserves the right to make changes in specifications and other information contained in this document and its website without prior notice. The reader should in all cases consult representatives of Extreme Networks to determine whether any such changes have been made.

The hardware, firmware, software or any specifications described or referred to in this document are subject to change without notice. Trademarks

Extreme Networks and the Extreme Networks logo are trademarks or registered trademarks of Extreme Networks, Inc. in the United States and/or other countries. All other names (including any product names) mentioned in this document are the property of their respective owners and may be trademarks or registered trademarks of their respective companies/owners. For additional information on Extreme Networks trademarks, please see:

www.extremenetworks.com/company/legal/trademarks