

# Ethernet Switch 460/470/470-PWR

Software Release 3.6.2.4/5

# 1. Release Summary

Release Date: 17-April-2006

Purpose: Software patch release to address a problem found in a Nortel lab.

# 2. Important Notes Before Upgrading to This Release

None.

# 3. Platforms Supported

Ethernet Switch 460/470

# 4. Notes for Upgrade

Nortel strongly recommends that users backup their ASCII configuration file before installing 3.6.2.4/5. For general information on how to upgrade your switch please see "Release Notes for the Ethernet Switches 460/470" (Part No. 217103-B, available at <a href="http://www.nortel.com/support">http://www.nortel.com/support</a>. Under Switches and Hubs, select Ethernet Switches, then Ethernet Switch 470-24T from the list of products) for details on how to upgrade your switch.

#### **File Names For This Release**

File Name	Module or File Type	File Size (bytes)
470_3624.img	Agent code image	2,365,113
470_3625s.img	Agent code image (SSH)	2,441,970

# 5. Version of Previous Release

Software Version 3.6.2.2/3

#### 6. Compatibility

This software release is managed with Java Device Manager (JDM) release 5.9.5.

©2006 Nortel Networks Limited Rev: 1.1 (19-Apr-2006) Page 1 of 2

# 7. Changes in This Release

New Features in This Release None.

Old Features Removed From This Release None.

#### **Problems Resolved in This Release**

Rectifies potential memory pointer corruption with 3.6.2.2 and 3.6.2.3 agent images that could sometimes lead to corruption of configuration image on the switch FLASH (Q01346471).

# 8. Outstanding Issues

#### 9. Known Limitations

None.

# 10. Documentation Corrections

For other known issues, please refer to the product release notes and technical documentation available from the Nortel Technical Support web site at: http://www.nortel.com/support.

Copyright © 2006 Nortel Networks Limited - All Rights Reserved. Nortel, Nortel Networks, the Nortel logo, Globemark, and product family> are trademarks of Nortel Networks Limited.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel.

To access more technical documentation, search our knowledge base, or open a service request online, please visit Nortel Technical Support on the web at: <a href="http://www.nortel.com/support">http://www.nortel.com/support</a>

©2006 Nortel Networks Limited Rev: 1.1 (19-Apr-2006) Page 2 of 2