+1 888-257-3000



Service Release Notes for WiNG 7.2.0.1-003R

Please Note: Service releases are made available to fix specific customer reported issues in a timely manner. Service releases are not as extensively tested as main releases (such as 7.2.0.0-017R). The next maintenance or manufacturing release will incorporate all qualifying and preceding service releases.

This document is an addendum to the release notes for the main release 7.2.0.0-017R.

CONTENTS

1. Resolved Issues	1
2. Important Notes	1
3. Platforms Supported	
4. Firmware Upgrade/Downgrade Procedure	

1. RESOLVED ISSUES

This service release 7.2.0.1-003R contains important fixes for Wi-Fi certification.

Following is a list of SPRs/CRs fixed in this release:

CRID	Description
WING-38734	Wi-Fi Certification: Traffic sent by the legacy STA to the WMM STA is transmitted as AC_BE (best effort) traffic from the APUT
WING-39220	Wi-Fi Certification: Key reinstallation vulnerability test on 802.11r AP fails
WING-39421	Wi-Fi Certification: AP denies association as it sees Invalid RSNIE

2. IMPORTANT NOTES

None.

3. PLATFORMS SUPPORTED

This release applies to all platforms released with WiNG 7.2.0.0-017R.



+1 888-257-3000

4. FIRMWARE UPGRADE/DOWNGRADE PROCEDURE

The method described in this section uses the Command Line Interface (CLI) procedures. To log into the CLI, either SSH, Telnet or serial access can be used.

For detailed upgrade procedure – please refer to WiNG 7.2.0 release notes.

<u>Upgrade from WiNG v7x.x.x to WiNG v7.2.0.1</u>

- 1. Copy the controller image to your tftp/ftp server.
- Use the —upgrade ftp://<username>:<password>@<ip address of server>/<name of file> , or
 —upgrade tftp://<ip address of server>/<name of file> command from CLI or Switch->Firmware>Update Firmware option from the GUI. You may need to specify the username and password for
 your ftp server.
- 3. Restart the controller. From CLI the command is —reload.

© Extreme Networks. 2019. All rights reserved.