

## Service Release Notes

### WiNG 5.9.8.3-003R

#### IMPORTANT

Service releases are made available to fix specific customer reported issues in a timely manner. Service releases are not as extensively tested as main releases such as **5.9.8.0-003R**. The next maintenance or manufacturing release will incorporate all qualifying and preceding service releases.

This document is an addendum to the release notes for the main release 5.9.8.0-003R.

#### Contents

Features.....	1
Fixed Issues .....	1
Platforms Support .....	2
Notes.....	2

#### Features

None

#### Fixed Issues

Following customer issues are fixed.

ESR/SPR	Description
WING-43218	Slow SNMP answers from NX9600
WING-43452	IPX: cfgd crash AttributeError: lpxRadio_Cfg object has no attribute meshpointbssmap
WING-43310	Captive-portal Preview Page error
WING-42807	AP8533 service packet capture session hang
WING-42828	Channel and RSSI always 0
WING-43438	2.4 radios have power set to 20 while SMART-RF limits to 10
WING-43463	AP7532 panic dns_snoop_age_entries
WING-42879	FA configuration being removed after receiving lldp packet from switch
WING-43599	AP7662 crash related to koda
WING-42549	AP7662 Core crash

## Platforms Support

Supported in this release,

AP8163, AP7502, AP7522, AP7532, AP7562, AP7602, AP7612, AP7622, AP7632, AP7662, AP8432, AP8533, RFS4000, NX5500, NX7500, NX9500, NX9600, VX9000

## Notes

None.